



Technical Information

**PLEASE PASS THIS IMPORTANT NOTE TO ALL OPERATORS OF YOUR
CG-3 GRAVIMETERS**

TECHNICAL NOTE #3 TO ALL CG-3 OWNERS

Re: Long Term Storage of Your CG-3

Page 6-12 of your Operator Manual advises how to store your Autograv when it is not expected to be used for some time. If these steps are followed, then the Autograv will be ready for use, when required, with minimal delay. It will be at its operating temperature and with a fully charged battery at all times, providing that it is connected to the powered-up battery charger.

Also, while in storage, the CG-3 should be set up on its tripod and levelled, so that the moving mass and the spring are in their normal measurement configuration. In this way, there will be no hysteresis effects due to the long term storage.

When you wish to resume active use of your CG-3 after long term storage, you should first update its long term drift correction (Page 6-1) and reset the drift correction start time.



Head Office

SCINTREX Limited
222 Snidercroft Road
Concord, Ontario, Canada L4K 1B5
Tel: +1-905-669-2280
Fax: +1-905-669-6403
e-mail: scintrex@scintrexltd.com
website: www.scintrexltd.com

In the U.S.A.

SCINTREX Inc.
900 Woodrow Lane, Suite 100
Denton, Texas
76205 U.S.A.
Tel: +1-940-591-7755
Fax: +1-940-591-1968
e-mail: richardj@scintrexusa.com

In S.E. Asia

SCINTREX / AUSLOG
P.O. Box 125 Sumner Park
83 Jijaws Street. Brisbane, QLD
Tel: +61-7-3376-5188
Fax: +61-7-3376-6626
e-mail: auslog@auslog.com.au
website: www.auslog.com.au